

Suite 1501, Northbrook Office Court 666 West Dundee Road, Northbrook, IL 60062 • (312) 498-9094

TECHNICAL ASSISTANCE TEAM FOR EMERGENCY RESPONSE REMOVAL AND PREVENTION EPA CONTRACT 68-01-6669

TO: Bob Bowden

26 April 1983

FROM: Technical Assistance Team

TAT-05-F-00130

VIA: Jack Thorsen

RE: Possible Emergency Action at Chicago/Santa Fe Property

TDD #5-8304-16

On 21 April 1983 TAT was tasked to conduct a preliminary assessment for a possible emergency action clean up of 57 drums near Kedzie Avenue and 34th St., Chicago.

TAT member Kevin Pierard met with Illinois EPA inspector Lynn Crevillo on 21 April to discuss the situation and review analyses. The IEPA received a complaint about the site on 3 March 1983. Analysis of four drums showed three with very low pH and one (fibre drum containing white powder) to have a very high pH. Samples from the three low pH drums were also analyzed for metals using EP Toxicity procedures. Metals, overall, were very high. No cyanide analysis was completed by the IEPA. The Illinois State Police Department of Criminal Investigation has (according to IEPA) accumulated a great deal of evidence and are confident they will find a responsible party.

On 22 April 1983 TAT members Kevin Pierard and Doug Ballotti met with Metropolitan Sanitary District (MSD) personnel at approximately 1330. MSD was providing site security during the day. At 1345 Lynn Crevillo (IEPA) arrived. It appeared that the drums were dumped at the top of a very steep embankment and allowed to roll down the embankment close to the Santa Fe railroad tracks. The IEPA estimates the drums have been at this location for well over a year. The drums were in very poor condition and most were leaking.

TAT entered the site in level "C" protection and tested approximately 10 drums that contained liquid using pH paper. All drums contained low pH material. A sample of the white powder, that IEPA had found to have a pH of 12.1 was mixed with acidic liquid from an adjacent drum in a sample jar. While mixing the two materials, the reaction was monitored with cyanide draeger tubes. The draeger tubes reaction was negative. A sample of this powder was obtained for cyanide analysis by the USEPA.

The area where the drums were dumped is heavily used by local residents for recreational activities. Because of frequent public use and the deteriorated condition of the drums there is a great potential for public contact with strong acids and bases.

IEPA analysis on the white powder for cyanide should be complete during the week of 25 April 1983. Pending results of the cyanide analyses, it should be noted that it is possible that cyanide bearing wastes could contact the acids on site.

Kevin Pierard

Doug Ballotti

KP/DB:js

1. COST CENTER:		INT OF COMPLETION	2. NO.: 5-8304-16
	b .	RTDD	The second secon
. 5		ICY RESPONSE, D PREVENTION	☐ COMPLETE ☐ INTERIM
		STON, INC.	
	NOT F. WE	STON, INC.	
3. RESPONSE: Submitted herewith is the completed report on TAT' assessment of the drums dumped at the Santa Fe property in Chicago. TAT determined that there is a high possibility of public exposure to highly acidic and basic solutions. Th			☐ LETTER REPORT ☐ FORMAL BRIEFING ☐ OTHER (SPECIFY)
	- · · · · · · · · · · · · · · · · · · ·	lytical results) cyanide	could be liberated
if drumed mat	erials are allowed to r	ZŽX.	
			
		. ,	
3A. ACTUAL TOTAL CO	ST:	3B. ACTUAL TOTAL HOURS	S:
4. DPO ACTION:	□ ACCEPTED □	ACCEPTED WITH EXCEPTION	NS □ REJECTED
5. COMMENTS:		·	
		,	
		·····	
6. I CERTIFY THAT THE A	ATTACHED MATERIALS MEET HE SUBJECT TDD.	FAND COMPLY WITH ALL	7. DATE:
	"Parameter of the control of the con		
	(TATI ALABIETIES)	<u>:</u>	
	(TATL SIGNATURE)		
8. I ACKNOWLEDGE THAT I HAVE BEEN PROVIDED WITH THE MATERIALS AND SERVICES SPECIFIED IN THE SUBJECT TDD WITHIN ITS ORIGINAL OR REVISED TIME FRAMES.		9. DATE:	
			·
•			
		NOTE OF THE PARTY AND ADDRESS OF THE PARTY AND	
(A	UTHORIZING DPO SIGNA	IURE)	

Sheet 1 White — TATL Copy
Sheet 2 Green — DPO Copy (Signed by TATL, Replaces Original)
Sheet 3 Canary — NPMC Copy
Sheet 4 Pink — Project Officer Copy
Sheet 5 Blue — Contracting Officer (Washington, D.C.)
Sheet 6 Goldenrod — DPO Original (Unsigned by TATL)


10	2
5	3

OIL/HAZARDOUS SUBSTANCES DISCHARGE REPORT

and the second of the second o

Ť.	DATE 6.2-87 TIME 2 PM SBY OFFICER BERNOTAS- VIA WRC
	PERSON_REPORTING/TITLE DAVE CLARK TELEPHONE: (913) 735-0041
	ORGANIZATION SANTE FE RR
	ADDRESS P.O BOX 1738 TOPEKA, KA 66628
3.	LOCATION (NEAREST CITY, STATE, SPECIFIC LOCATION) KINGSVICCE TX TO
	CHICAGO, IL
	TOWN RANGE COUNTY
	TIME/DATE OF INCIDENT 5-31-82 0200
	BODY OF WATER AFFECTED NONE
6.	SOURCE (FACILITY, EQUIPMENT) TANK CAR
7.	CAUSE/OPERATION IN PROGRESS DEFECTIVE VAULE PACKING
_	
8.	MATERIAL METHYLE KETHYLE KETON QUANTITY DISCHARGE 87 GAL
10.	QUANTITY IN WATER/SLICK SIZE AND COLOR
11.	ACTIONS TAKEN (SECURING/CONTAINMENT/REMOVAL) VAUGE SHUT - NOTIFIED
12.	OTHER AGENCIES NOTIFIED BY CALLER CALL FIRE DEPT, SHIPPER
13.	NOTES CHEMTRIC, JUNEAUC OF EXPLOSIVE
14.	ACTIONS TAKEN BY SBY OFFICER: NONE REQUIRE - SB

Son to Fe



TDD# 5-8304-16 Chicago/Santa Fe

4/22/83 3;00 pm


Picture shows drums at top of embankment looking to the Northeast



TDD # 5-8304-16 Chicago/ Santa Fe

4/22/83 3:02pm

Picture shows drums and spillage at base of embankment. Picture taken looking North



TDD# 5-8304-16 Chicago/Santa Fe

4/22/83 3:04 pm


Picture shows drums on embankment and plating vat at the base. Picure taken looking Northeast



TDD# 5-8304-16 Chicago/ Santa Fe

4/22/83 3:10pm


Picture shows drums and spillage on embankment looking Northeast.



TDD# 5-8304-16 Chicago/ Sante Fe

4/22/83 3:15pm

Drums at base of embankment looking North from SEGG end of site.



TDD# 5-8304-16 Chicago/ Sante Fe

4/22/83 3:20pm

Drums at base of embankment looking Northeast from Southeast end of site.